



HI-FLO® ES (ENERGY SAVER) PRODUCT PERFORMANCE GUARANTEE

The Camfil Hi-Flo ES (Energy Saver) comes fully guaranteed to last as long or longer without requiring a prefilter while providing energy savings and performing better than traditional filters. This unique product design was developed solely for sustainability performance including energy savings, reduced waste, and reduced carbon footprint. No other filter can perform like the Hi-Flo ES. The product guarantee is as follows:

GUARANTEE: Camfil guarantees that the Hi-Flo ES (in any efficiency configuration) will last 12 months or longer without a prefilter. The Hi-Flo ES maintains lifetime efficiency by using a special fine fiber media. This guarantees the MERV rating will be maintained throughout the installed life of the filter, providing consistent and sustainable quality indoor air. *(Products made of charged coarse fiber media have been proven to have a rapid reduction in MERV rating once installed in an air handler.)*

CONDITIONS: Guarantee is based on a maximum of 400 FPM airflow and a final pressure drop not-to-exceed 1.5" water gauge. If the Hi-Flo ES fails to last at least 12 months, the following conditions will apply:

- The customer must contact Camfil to provide details of the installation. Requested information will include the customer name, shipping address, a contact name, a contact telephone number, the distributor that provided the filters, application information, the manufacturer and type of the previously used filters, and a description of the service life comparison.
- Camfil will directly ship a complete set of replacement Hi-Flo ES filters to the customer — up to a maximum quantity of 24 units.
- If the value of the replacement filters exceeds \$500.00, a Camfil distributor or representative must visit the site to verify the accuracy of the information.
- Once the information has been verified in writing to Camfil, the replacement order will be shipped.
- A user may only qualify for one replacement set of filters.
- Disclaimers and exclusions that will apply include: Premature filter failure caused by mechanical damage or failure of the HVAC system; premature filter failure due to physical damage to the Hi-Flo ES caused by human intervention; premature filter failure due to application of the filter where differential pressure across the filter exceeds the published maximum recommended final pressure drop of 1.5" w.g.

**If the Hi-Flo ES does not perform to the above standards,
Camfil promises to provide you one free set of replacement filters.**

Contact us at 1-866-4CAMFIL